

ESTIMATE REPORT

FORM R 70979 7

Customer No

Model No

Five Points Sport Shop, Inc.

P. O. Box 132

ROUTE 512 — BANGOR, PENNSYLVANIA 15013

315-888-4143

Remington Arms:

GUN FIRES when safety mechanism
is disengaged, before trigger function
is employed. This happened when
RIFLE WAS still in MANUFACTURERS Condition,
CAUSING A discharge in the buyers home.
PLEASE REPAIR. IF ANY CHARGE notify:

John L. Zeruth, mgr.
Five Points Sport Shop

John L. Zeruth mgr.