

RECEIVING AND ESTIMATING REPORT ✓

INITIAL JJM		CUSTOMER ORDER NO.		COMMENTS			
DATE RECEIVED 12/07/90	DATE OPENED 12/13/90	DATE CODE EF 10-85	SERIAL NUMBER B6752073				
ACCESSORIES W/STUDS							

FROM: <div style="border: 1px solid black; padding: 5px; margin: 5px auto; width: 80%;"> FLEURY'S SPORTING GOODS RT 202 BOX 331 WINTHROP ME 04364 </div>	SHIP TO: <div style="border: 1px solid black; padding: 5px; margin: 5px auto; width: 80%;"> FLEURY'S SPORTING GOODS RT 202 BOX 331 WINTHROP ME 04364 </div>
---	--

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE <input type="checkbox"/>	CLEAN/TEST	PROM. DATE	ESTIMATED	VIA UPS
----------------	--------------------	--------------------------------	------------	------------	-----------	-------------------

REPAIR CHARGE	TAX	INSURANCE	UPS	PARCEL POST	TOTAL
---------------	-----	-----------	-----	-------------	-------

GUN CONDITION: NEW SLIGHTLY WORN VERY WORN MISUSED MARRED

CUSTOMER'S REQUEST
"Customer took safety off, gun would not fire, put safety on & off a few times, then gun discharged without pulling trigger"

MAIN FAULT
Could not duplicate complaint, however, trigger assembly has been improperly adjusted outside factory. Sealant missing from all adjustment screws. Trigger pull medium to heavy, insufficient over-travel, excessive rear-engagement. Tip has been broken off safety detent spring.

PARTS
Send repair quotation for new trigger assembly at 1/2 normal price, as gesture of good-will.

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE