

Customer Complaint

P.I. No GUN IDENTIFICATION REPORT NUMBER: \_\_\_\_\_ MODEL: 700 S&W  
 GENERAL CONDITION: Good R # : 24953  
 OUTSIDE WORK: No DATE: 10-28-70  
 FROM: FLOODWOOD - MINN.  
 FIRED AMMO TYPE: \_\_\_\_\_ GUN # : 6837951  
 & CONDITION: \_\_\_\_\_ CODE: CT = 4/70  
 PROOF: R.E.P. INSP.: \_\_\_\_\_ TEST: \_\_\_\_\_ GA./CAL.: 25-06  
 HEADING: O.K. CHECKED BY: C. PROFFER  
 BREECH OPENING: \_\_\_\_\_ APPROVED: \_\_\_\_\_  
 RECOIL SHOULDERS: \_\_\_\_\_ APPROVED: \_\_\_\_\_  
 CHAMBER: O.K. APPROVED: \_\_\_\_\_  
 TEST: No APPROVED: \_\_\_\_\_  
 COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: \_\_\_\_\_

COMPLAINT: "BULLET STICKS IN CHAMBER ALSO BOLT IS IMMOVABLE FOR SOME REASON."

INCIDENT: \_\_\_\_\_

COMMENTS: THE CUSTOMER PULLED THE BULLET OUT OF THE CASE LEAVING IT IN THE THROAT. THIS APPARENTLY IS AN AMMUNITION PROBLEM (PER M. WALKER).  
THE BOLT CATCHING IS CAUSED BY PUSHING THE SAFETY ON BEFORE LOCKING THE BOLT THUS CATCHING THE SAFETY ARM IN THE COCKING CAM.