



REMINGTON ARMS COMPANY, INC.



MANUFACTURERS OF

SPORTING FIREARMS. AMMUNITION

SPORTING FIREARMS

TRAPS

POWDER METAL PARTS

ILION, NEW YORK

AMMUNITION, BRIDGEPORT, CONNECTICUT

LONOKE, ARKANSAS

TRAPS

TARGETS

ILION, NEW YORK 13357

TELEPHONE (315) 894-9961

PETERS CARTRIDGE DIVISION

BRIDGEPORT, CONNECTICUT

TARGETS, ADA, OKLAHOMA

ATHENS, GEORGIA

RINDLAY, OHIO

CABLE—HARTLEY, BRIDGEPORT

September 14, 1984

Mr. Dixon H. Fotheringham
667 N. 1050 W.
St. George, Utah 84770

Dear Mr. Fotheringham:

Your letter of August 21, 1984 that was addressed to our Bridgeport, Connecticut facility, regarding the accidental firings you have experienced while releasing the safeties on two (2) Model 700 rifles that you own, has been forwarded to this office for handling.

We were indeed sorry to learn of your having a problem of this nature, as it is not characteristic of the Model 700 rifle.

Generally, the type of malfunction you described results from either improper adjustment of the trigger assembly outside our factory, from improper maintenance of the rifle, or, from pressure being inadvertently applied to the trigger at the instant the safety is released.


Please, at your convenience, return the rifles via insured and collect transportation, to:

Remington Arms Company, Inc.
Attn: Mr. J.A. Stekl
Supervisor Product Service
Ilion, New York 13357

Upon receipt, we will thoroughly examine the firearm and, if they are found to be factory faulty, any necessary repairs will be made on a no-charge basis.

Thank you for bringing this matter to our attention and for having afforded us this opportunity to be of service to you.

Sincerely,


J.A. Stekl, Supervisor
Product Service

JAS:tpg