

P S. #1498

RECEIVED

SEP 4 1984

CONSUMER SERVICE

Dixon H. Fotheringham  
667 N. 1050 W.  
St. George, Utah 84770

Aug. 21, 1984

RECEIVED

SEP 4 1984

J. A. STEKL

Remington Arms Co, Inc.  
Bridgeport, CT 06601

Gentlemen:

I am a Remington Gun fan and own four of them. Two Model 370 "Special Field" shot guns, and two Model 700 EDL<sup>i</sup> rifles. One in .30/06 calibre and one in .243 calibre.

I am having trouble with both of the Model 700 rifles in that they quite often discharge when letting off the safety. This is very unsafe when hunting with a group.

Is there something that can be done about this problem? If so, where in this area?

Very truly & concerned yours,

  
Dixon H. Fotheringham