

M/700 Customer Complaint

P.I. No GUN EXAMINATION REPORT NUMBER: _____

MODEL: 700

GENERAL CONDITION: NEW

R #: 016257

OUTSIDE WORK: NO

DATE: 8-16-72

FROM: HENRY L. FRAME

FIRED AMMO TYPE: -

W. BARRINGTON, R.I.

& CONDITION: _____

GUN #: 297377

PROOF: R.E.P. INSP.: 1A TEST: 49

CODE: WR = 8/68

HEADING: _____

GA./CAL.: 270 WIN.

BREECH OPENING: -

CHECKED BY: C. PROSSER

RECOIL SHOULDERS: O.K.

APPROVED: _____

CHAMBER: O.K.

APPROVED: _____

TEST: NO

APPROVED: _____

COMPONENT CONDITION: (Damaged, Broken, Old Style)

APPROVED: _____

TRIGGER PULL 3 1/2 LBS., SEAR-TRIGGER CONNECTOR
ENGAGEMENT .005 (MIN. IS .020) STICKY LUBRICANT
INSIDE HOUSING, CORNER OF TRIGGER CONNECTOR
WORN ROUND.

COMPLAINT: "IT DISCHARGES PREMATURELY"

INCIDENT: FOLLOW DOWN

COMMENTS: WITH INSUFFICIENT ENGAGEMENT BETWEEN
SEAR & CONNECTOR THE CONNECTOR BROKE DOWN
ON THE CORNER ALLOWING THE FOLLOW DOWN
MAJFUNCTION.