

*Cust Comp.*

P.I. NO GUN EXAMINATION REPORT NUMBER: \_\_\_\_\_ MODEL: 700 BDL

GENERAL CONDITION: FAIR R #: 000014

OUTSIDE WORK: SCOPE MOUNTED, BUTT PAD ASSEMBLY, FITTED. SEALS REMOVED - TRIGGER DATE: 1-4-73

FIRE AMMO TYPE: - FROM: W.K. FRAYSUR HOUSTON, TEXAS

& CONDITION: \_\_\_\_\_ GUN #: 69329

PROOF: R.E.P. INSP.: 5 TEST: 13 CODE: PK-5/63

HEADING: ? GRA./CAL.: 270

BREECH OPENING: - CHECKED BY: C. PROSSER

RECOIL SHOULDERS: O.K. APPROVED: \_\_\_\_\_

CHAMBER: - APPROVED: \_\_\_\_\_

TEST: NO APPROVED: \_\_\_\_\_

COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: \_\_\_\_\_

EXCESSIVE LUBRICANT, TRIGGER BIND ON TRIGGER GUARD POSSIBLE.

COMPLAINT: "WILL FIRE ACCIDENTALLY ON PUSHING OFF THE SAFETY"

INCIDENT: FOLLOW DOWN

COMMENTS: THE CUSTOMER'S MALFUNCTION NOT DUPLICATED, IT PROBABLY IS ASSOCIATED WITH TRIGGER BIND AND TYPE OF LUBRICATION USED.