

*Carl Conzel*

F.I. NO GUN EXAMINATION REPORT NUMBER: \_\_\_\_\_ MODEL: 700BOL

GENERAL CONDITION: NEW R #: 024573

OUTSIDE WORK: SCOPE & RECOIL PAD FITTED. DATE: 11-27-72

FROM: FRONTIERSMAN SPORTS INC.

FIRE AMMO TYPE: - MINNEAPOLIS, MINN.

& CONDITION: \_\_\_\_\_ GUN #: 6365254

PROOF: R.E.P. INSP.: 74 TEST: 49 CODE: DT = 9/70

HEADING: O.K. SK./CAL.: 3006

BREECH OPENING: - CHECKED BY: C. PROSSER

RECOIL SHOULDERS: O.K. APPROVED: \_\_\_\_\_

CHAMBER: O.K. APPROVED: \_\_\_\_\_

TEST: NO APPROVED: \_\_\_\_\_

COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: \_\_\_\_\_

SEAR-TRIGGER CONNECTOR ENGAGEMENT .005 (MIN. = .020)

TRIGGER CONNECTOR CLEARANCE ON TRIGGER = 1.075,

M/D = <sup>1.076</sup> 1.079; TRIGGER CLEARANCE ON CONNECTOR = 1.096,

M/D = <sup>1.080</sup> 1.083. FIRING PIN CAN CATCH ON REAR CORNER

OF HOUSING. LAPPING ON CONNECTOR CROOKED.

COMPLAINT: RIFLE DISCHARGED WHEN LOADING CARTRIDGE.

INCIDENT: FOLLOW DOWN

COMMENTS: THERE IS EVIDENCE OF TRIGGER BIND. THIS COMBINED WITH UNDER MIN. ENGAGEMENT AND EXCESSIVE TRIGGER-CONNECTOR CLEARANCE, CAUSES FOLLOW DOWN.