

# RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER R 92-0997

INITIAL CUSTOMER ORDER NO.

BOTTOM HALF OF MOUNTS ONLY

STEKL

DATE RECEIVED 04/07/92 DATE OPENED 04/15/92 DATE CODE AG 3-86 SERIAL NUMBER B6778078 NEW SERIAL NUMBER MODEL AND GRADE 700 270 MTN

ACCESSORIES W/STUDS SCOPE BASE

FROM:

FURLONG, JIM  
RD 2 SILVER CREEK RD  
JOHNSONBURG PA 15845

SHIP TO:

FURLONG, JIM  
RD 2 SILVER CREEK RD  
JOHNSONBURG PA 15845

CUST NO: 060923 C.O.D.

ACCOUNT NUMBER ACCOUNT NUMBER N/C WRITE  CLEAN/TEST PROM. DATE ESTIMATED 4/28/92 VIA UPS

GUN CONDITION

- NEW
- LIGHTLY WORN
- WORN
- VERY WORN
- UNREPAIRABLE
- MARRED

REPAIR CHARGE

EXCISE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	B1				
TRIGGER GROUP		B2			E1	
BOLT ASSY.		B3			E2	F2
BARREL ASSY.		B4		D1	E3	F3
REC. ASSY.		B5		D2	E4	F4
WOOD			C1	D3	E5	F5
METAL			C2			

MAIN FAULT

Complaint was duplicated, also, at times the firing pin followed down as the action was closed. Disassembly of the rifle revealed that the trigger assembly had been improperly adjusted. Trigger pull was only 3.5 pounds, and the adjustment seemed to be correct. It was found that the main spring for the trigger was broken.

Serial # 0124

PARTS

COMMENTS

Offer to re-adjust present trigger assembly, or to install new trigger assembly at a normal cost, as a gift of goodwill, if that will provide me recognition in the rfr.

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATT
W. H. H.					
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE