

**Remington.****REMINGTON ARMS COMPANY, INC.**

SPORTING ARMS-AMMUNITION-TARGETS-TRAPS

MILTON, NEW YORK 13357

TELEPHONE (315) 894-9961

January 26, 1989

Gauldin's Sports Center  
Attn: Mr. Bob Hill  
Route 10, Box 680A2  
Anniston, AL 36701

Dear Mr. Hill:

Examination has been completed on the Model 700 BDL 30-06 caliber rifle, serial number B6814960, that you returned to us because of various firing problems our customer encountered with it.

The returned firearm, which was produced in September of 1986, has been thoroughly examined and found to contain our high-pressure proof test, gallery test, and final inspection stampings, indicating that it had successfully passed all our necessary tests and inspections prior to shipment from our factory.

The general condition of the gun appeared to be very good and, in going over the individual parts, we found the headspace, recoil shoulders and chamber all to be normal.

Examination of the rifle and trigger assembly could not produce any malfunctions. All tolerances and dimensions were found to be normal. Also, factory seals were intact on the trigger adjustment screws, indicating no alterations were made to the trigger assembly outside our factory. Trigger pull was measured to be 5 pounds, and the sear-lift with the safety in the "on-safe" position was also well within specifications at .011".

Removal of the barreled-action from the stock revealed that the trigger assembly contained an excessive amount of lubrication.