

Mr. Sienkiewicz -

12-10-18

2/27/78

DEB GEIER

28 POTLATCH IDAHO

6771922

04-7-74

... 3006

D BY: M-HARDY

1/12/79

1/12/79

1-12-79

1-12-79

RUSTY REC.

*R.B. 1-12-79*

This Remington 30.6 (model 700) has fired when the safety was released. The gun was loaded, the trigger was not bumped, squeezed, or pulled... (nor was the gun)

As a result, our carpet & floor now has a hole in it. I figure \$50.00 would compensate for damages & repairs.

I do hope the gun can be fixed.

Thank you.  
Deb Geier

phone #  
208) 875 0304

Box 228  
Potlatch  
Idaho  
83855

RELEASED

LOOR

malfunction