

P.I. NO GUN EXAMINATION REPORT NUMBER: 50

MODEL: 700 BDL

GENERAL CONDITION: NEW

R #: 29532

OUTSIDE WORK: SCOPE MOUNTED

DATE: 12-8-82

FIRED AMMO TYPE: UNKNOWN

FROM: GELONSON, Inc.,
9625 Redwood Hwy.,
Bellevue, WA 98106

& CONDITION: _____

GUN #: B6330831

PROOF: R.E.P. INSP.: 115 TEST: 118

CODE: 5-01

HEADING: O.K.

GA./CAL.: .30-06 Spec.

BREECH OPENING: O.K.

CHECKED BY: [Signature]

RECOIL SHOULDERS: O.K.

APPROVED: [Signature] 1/11/83

CHAMBER: O.K.

APPROVED: [Signature] 1/11/83

TEST: —

APPROVED: [Signature] 1/11/83

COMPONENT CONDITION: (Damaged, Broken, Old Style)

APPROVED: _____

NEW

COMPLAINT: "... WHEN YOU PULL THE Bolt UP TO UNLOAD THE GUN,
THE SHELLS FIRE."

INCIDENT: _____

COMMENTS: Gun fails track test, fire control appears to
full of crud impeding proper function of trigger
& other fire control parts. Front adjusting screws
have sealant removed.
Trigger pull 5 1/2 #
Sealant .0105 - mill .0055
Replace fire control. - No change [Signature]