

RECEIVING AND ESTIMATING REPORT

ORDER R 92-02928

INITIAL: FPS CUSTOMER ORDER NO: 073502 COMMENTS: SERIAL NUMBER: C6238707 NEW SERIAL NUMBER: MODEL AND GRADE: 700 22-250 BDL
 DATE RECEIVED: 01/16/92 DATE OPENED: 01/23/92 DATE CODE: LI 2-88 ACCESSORIES: W/STUDS SCOPE BASE L/SIGHTS

FROM: GEM SPORTS SUPPLY CO. 625 BURNETT AVE. SYRACUSE NY 13203
 SHIP TO: GEM SPORTS SUPPLY CO. 625 BURNETT AVE. SYRACUSE NY 13203

CUST NO: 004064 ILION L
 ACCOUNT NUMBER: PROM. DATE: ESTIMATED: 2-10 VIA: UPS
 WRITE: CLEAN/TEST

- GUN CONDITION
- NEW
- LIGHTLY WORN
- WORN
- VERY WORN
- UNREPAIRABLE

REPAIR CHARGE
EXCISE
TAX
INSURANCE
UPS
PARCEL POST
TOTAL

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	B1	C1	D1	E1	F1
TRIGGER GROUP		B2	C2	D2	E2	F2
BOLT ASSY.		B3	C3	D3	E3	F3
BARREL ASSY.		B4	C4	D4	E4	F4
REC. ASSY.		B5	C5	D5	E5	F5
WOOD			C1	D3	E5	F5
METAL			C2			

MAIN FAULT: As received, rifle would not work. Disassembly of rifle revealed that the trigger assembly has been improperly adjusted (as evidenced by red coolant on rear engagement arms) - insufficient rear engagement. Trigger pull 7.5# - well below our minimum spec.

PARTS: COMMENTS: Send quotation for replacement trigger assembly at a minimal cost as getting good-will.
 Note - warn customer about adjusting trigger outside factory

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
BWT					
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6925 REV. 8/91