

*Customer Complaint*

P.I. NO GUN EXAMINATION REPORT NUMBER: \_\_\_\_\_ MODEL: 700

GENERAL CONDITION: GOOD R #: 19457

OUTSIDE WORK: SCOPE MOUNTED. DATE: 10-4-71

FROM: GEN. SPT. SUPPLY CO.

FIRED AMMO TYPE: - SYRACUSE, N.Y.

& CONDITION: \_\_\_\_\_ GUN #: 6279663

PROOF: R.E.P.-E ASSEMBLER 79 INSP.: 74 TEST: 87 CODE: ES = 10/69

HEADING: O.K. GR./CAL.: 3006

BREECH OPENING: - CHECKED BY: G. PROSSER

RECOIL SHOULDERS: O.K. APPROVED: \_\_\_\_\_

CHAMBER: O.K. APPROVED: \_\_\_\_\_

TEST: NO APPROVED: \_\_\_\_\_

COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: \_\_\_\_\_

NO DAMAGED OR BROKEN COMPONENTS.

COMPLAINT: FIRES WHEN SAFE IS PUSHED OFF.

INCIDENT: \_\_\_\_\_

COMMENTS: THE CUSTOMER'S MALFUNCTION COULD NOT BE DUPLICATED ANY WAY. IT WAS NOTED AND VERIFIED BY K. CHADWICK THAT THE CUSTOMER HAD APPLIED A LUBRICANT WHICH IS TOO HEAVY (THICK) TO THE TRIGGER ASSEMBLY. THIS, IN COLD CLIMATES WOULD CAUSE A MALFUNCTION SUCH AS THAT CLAIMED BY THE CUSTOMER.