

RECEIVED  
APR 25 1983

# RECEIVING AND ESTIMATING REPORT

DATE RECEIVED 3-30-83 ESTIMATED 4-25-83 <sup>965</sup> ORDER # R10815  
 DATE OPENED 3-31-83 VIA U.F.3.  
 MODEL AND GRADE 700 BDL-LH-270 Win SERIAL NO. B6368630  
W/Scope mounts DATE CODE KC 5-82

FROM:

Gibbs Party Store  
 6469 South Morey Rd.  
 Mc Bain, Michigan  
 49657

REPAIR CHARGE 043980-55  
 INS. \_\_\_\_\_  
 UPS \_\_\_\_\_  
 PARCEL POST \_\_\_\_\_  
 TOTAL \$ \_\_\_\_\_

GUN CONDITION: (NEW) (SLIGHTLY WORN) (VERY WORN) (MISUSED) (QUOTE)

CUSTOMER'S COMPLAINT Bolt lock softly installed

MAIN FAULT Gun has new style Trigger Assem. Customer want Bolt lock softly installed. Could find no fault with Gun.

PARTS	DEMERIT CODE
<u>32895-Trigger Assem. L.H</u>	<u>Fit old style Trigger Assem. in Exchange</u>
	<u>Polished Chamber</u>
	<u>Closed Action</u>
	<u>Work done</u>

FOR COMPUTER REFER. ONLY

--	--	--	--

PROOF \_\_\_\_\_  
 (CLEAN) (TEST) (TARGET) no