


Trigger pull was measured to be 4 1/2 pounds, sear lift with the safety in the "on-safe" position was well within specification at .009", as was sear-connector engagement. The only manner in which the rifle could be made to fire was with the safety off and the trigger pulled, as designed.

Since we found the firearm to function normally in every respect, we are prepared to return it in its present condition. However, a trigger assembly with a safety that allows the bolt to be opened with the safety on, can be installed for \$35.00 net.

Should you desire the new trigger assembly, please include a check in the above amount made out to Remington Arms Company, Inc., with your response marked to my attention. We will await your decision and reply.

Thank you for affording us the opportunity to examine your rifle and report our findings.

Sincerely,



J.A. Stekl
Specialist
Product Service

JAS/nb

Remington Arms Company, Inc.