

RECEIVING AND ESTIMATING REPORT

R 93-01945

INITIAL L.H.	CUSTOMER ORDER NO.		ATTN DENNIS SANITA			
DATE RECEIVED 01/20/93	DATE OPENED 01/20/93	DATE CODE LG 2-86	SERIAL NUMBER B6772566	NEW SERIAL NUMBER	MODEL AND GRADE 700 243	RDL
ACCESSORIES W/STUOS						

FROM:	SHIP TO:
GOULD, LEONARD G 126 COOLIDGE AVE LEHIGH ACRES FL 33936	GOULD, LEONARD G 126 COOLIDGE AVE LEHIGH ACRES FL 33936

CUST NO: 073742 C-D.DL

ACCOUNT NUMBER 059015	ACCOUNT NUMBER-VC	WRITE <input type="checkbox"/>	CLEAN/TEST	PROM. DATE	ESTIMATED	VIA UPS
--------------------------	-------------------	--------------------------------	------------	------------	-----------	------------

GUN CONDITION <input checked="" type="checkbox"/> NEW <input type="checkbox"/> LIGHTLY WORN <input type="checkbox"/> WORN <input type="checkbox"/> VERY WORN <input type="checkbox"/> UNREPAIRABLE <input type="checkbox"/> MARRED	REPAIR CHARGE	
	EXCISE	
	TAX	
	INSURANCE	
	UPS	
	PARCEL POST	
	TOTAL	

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	B1				
TRIGGER GROUP					E1	F1
BOLT ASSY.		B3			E2	F2
BARREL ASSY.		B5			E3	F3
REC. ASSY.			D2		E4	F4
WOOD						F5
METAL			C2			

Purchased new 11/92
Always received owners manual or gun box, front sight ramp missing.
Call Mfg 3/86 Unable to duplicate Customers Concern.
Trigger pull 4 1/2 lbs, weight .015, both within specifications.
Front sight ramp missing, stock cracked at rear of trigger guard.

ARTS

COMMENTS

1/24/93 discussed findings with customer via phone
Agreed to get new trigger assembly to be, front sight in rft, get new stock ramp and replace front sight ramp. no further good will.

REPAIRMAN	TROOP	CLEAN	TEST	TARGET	PATTER
		<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>		
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6925 REV. 1