

15-61

*Cost Complaint*

EXAMINATION REPORT NUMBER: \_\_\_\_\_

MODEL: 700

CONDITION: NEW

R #: 02598

OUTSIDE WORK: NO

DATE: 12-7-72

FROM: GRAF & SONS INC.

FIRED AMMO TYPE: -

MEXICO, MO.

& CONDITION: \_\_\_\_\_

GUN #: 643949.3

PROOF: R.E.P.-L INSP.: 73 TEST: 53

CODE: KU=5/71

HEADING: O.K.

GA./CAL.: 25-06

BREECH OPENING: -

CHECKED BY: CIPROSSER

RECOIL SHOULDERS: O.K.

APPROVED: \_\_\_\_\_

CHAMBER: O.K.

APPROVED: \_\_\_\_\_

TEST: NO

APPROVED: \_\_\_\_\_

COMPONENT CONDITION: (Damaged, Broken, Old Style)

APPROVED: \_\_\_\_\_

SEAR-TRIGGER CONNECTOR ENGAGEMENT, 0.10 (MIN. 15.020)

BURRS ON SIDE OF TRIGGER.

COMPLAINT: "GUN GOES OFF WHEN BOLT IS CLOSED."

INCIDENT: FOLLOW DOWN

COMMENTS: THE CUSTOMER'S MALFUNCTION NOT DUPLICATED,  
HOWEVER THE TRIGGER BIND COMBINED WITH UNDER  
MIN. ENGAGEMENT MAY HAVE CAUSED A FOLLOW  
DOWN.