

*Customer Complaint*

P.I. No GUN EXAMINATION REPORT NUMBER: \_\_\_\_\_ MODEL: 660

GENERAL CONDITION: NEW R # : 15018

OUTSIDE WORK: No DATE: 7-28-71

FROM: R.J. GRAMAZIO

FIRED AMMO TYPE: — YARMOUTH, MASS.

& CONDITION: \_\_\_\_\_ GUN # : 6210588

PROOF: R.E.P. ASSEMBLER #14 INSP.: 96 TEST: 32 CODE: LS = 2/69

HEADING: O.K. GA./CAL.: .308

BREECH OPENING: — CHECKED BY: C. PROSSER

RECOIL SHOULDERS: O.K. APPROVED: \_\_\_\_\_

CHAMBER: O.K. APPROVED: \_\_\_\_\_

TEST: No APPROVED: \_\_\_\_\_

COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: \_\_\_\_\_

NO BROKEN ETC. COMPONENTS. TRIGGER CONNECTOR-SEAR ENGAGEMENT = .005 (.020 MIN.). SLIGHT UPSET AT LEFT REAR CORNER OF HOUSING CAUSED BY THE FIRING PIN HEAD CATCHING ON IT.

COMPLAINT: "GUN WENT OFF JUST PUTTING A SHELL IN THE CHAMBER"

INCIDENT: FOLLOWED DOWN

COMMENTS: THERE WAS NOT ENOUGH ENGAGEMENT BETWEEN THE TRIGGER CONNECTOR AND SEAR. THIS BEING REDUCED TO ALMOST ZERO BY A SLIGHT TRIGGER BIND, LED TO THE CUSTOMER'S MALFUNCTION.