

RECEIVING AND ESTIMATING REPORT

COMMENTS

W/HUNTER FIBERGLASS STOCK

R 92-04506 ORDER

INITIAL JJM	CUSTOMER ORDER NO.				
DATE RECEIVED 02/03/92	DATE OPENED 02/06/92	DATE CODE PH 6-87	SERIAL NUMBER B6867503	NEW SERIAL NUMBER	MODEL AND GRADE 700 270
ACCESSORIES W/STUDS					

FROM: **GRAMKE, KORB**
6029 W 38TH SO CT
WICHITA, KS 67215

SHIP TO: **GRAMKE, KORB**
6029 W 38TH SO CT
WICHITA, KS 67215

CUST NO: 057759 C.O.D.

ACCOUNT NUMBER	ACCOUNT NUMBER MC	WRITE <input type="checkbox"/>	CLEAN/TEST	PROM. DATE	ESTIMATED	VIA UPS
----------------	-------------------	--------------------------------	------------	------------	-----------	-------------------

- GUN CONDITION
- NEW
 - LIGHTLY WORN
 - WORN
 - VERY WORN
 - UNREPAIRABLE

[Large blank area for handwritten notes]

REPAIR CHARGE
EXCISE
TAX
INSURANCE
UPS
PARCEL POST
TOTAL

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	B1	Fired when safety was disengaged			
TRIGGER GROUP		B2			E1	F1
BOLT ASSY.		B3			E2	F2
BARREL ASSY.		B4		D1	E3	F3
REC. ASSY.		B5		D2	E4	F4
WOOD			C1	D3	E5	F5
METAL			C2			

MAIN FAULT *Could not duplicate complaint - trigger assembly operates properly. However, safety "off" jam required does appear to be high for some reason.*

Trigger pull 5 1/2#, var-lyft .0115"

PARTS	COMMENTS
	<i>Replace trigger - safety assembly at 700 - change, as gesture of good-will, even though lyft in 4 1/2 years old</i>

REPAIRMAN <i>[Signature]</i>	PROOF	CLEAN	TEST	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE