

ATTN: REPAIRS

PLEASE FIND ENCLOSED ONE REM MODEL 700 KIT GUN IN 270 CAL WITH BLACK RAM LINE STOCK & SLING S/N B6867503.

SQUACK: WHEN THE SAFETY WAS DISENGAGED THE GUN FIRED THIS HAPPEND AFTER SEVERAL UNEVENTFUL SHOTS. I HAVE HAD THIS MODEL 700 FOR FOUR YEARS NOW AND HAVE NEVER HAD THIS HAPPEN BEFORE.

NEVER-THE-LESS EVERY SINCE I HAVE OWNED THIS GUN THE SAFETY HAS BEEN VERY ROUGH AND HARD TO DISENGAGED THIS PROBLEM COULD HAVE CAUSED A SERIOUS INJURY. I ASSURE YOU THIS MISFIRE WAS CAUSED BY THE FORCE NEEDED TO DISENGAGE THE SAFETY.

THIS WAS NOT CAUSED BY THE OPERATOR HAVING HIS FINGER ON THE TRIGGER AT THE SAME TIME AS DISENGAGING THE SAFETY. THERE WERE THREE WITNESSES WATCHING THIS INCIDENT AND ALL THREE AGREE THAT HIS FINGER WAS OFF THE TRIGGER. IT WAS OFF BECAUSE THE FORCE NEEDED TO REMOVE THE SAFETY REQUIRED A HEAVY THUMB.

INSPECT AND REPAIR AS NECESSARY.
IF ANY REPAIR CHARGES ARE TO BE BILLED TO ME PLEASE CALL BEFORE PROCEEDING.

HOME 316-524-6705
WORK 316-529-9546

Korby Gramke
KORBY GRAMKE