

Cost Camp

P.I. No GUN EXAMINATION REPORT NUMBER: _____ MODEL: 700

GENERAL CONDITION: Good R #: 023332

OUTSIDE WORK: No DATE: 11-13-72

FIRED AMMO TYPE: - FROM: GRANTS' FOR GUNS INC. COSTA MESA, CAL.

& CONDITION: _____ GUN #: 6449597

PROOF: REP-N ^{ASSEMBLER 73} INSP.: 87 TEST: 53 CODE: WV = 8/71

HEADING: O.K. GR./CAL.: 3006

BREECH OPENING: _____ CHECKED BY: CIPROSSER

RECOIL SHOULDERS: O.K. APPROVED: _____

CHAMBER: O.K. APPROVED: _____

TEST: No APPROVED: _____

COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____

SEAR-TRIGGER CONNECTOR ENGAGEMENT = 0.10
(MIN. IS .020) BURRS ON SIDES OF TRIGGER

COMPLAINT: GUN FIRES WHEN SAFETY IS TAKEN OFF.

INCIDENT: FOLLOW DOWN

COMMENTS: IT APPEARS THAT TRIGGER BIND MAY HAVE PREVENTED FULL RETRACTION OF CONNECTOR UNDER THE SEAR REDUCING THE UNDER MIN. ENGAGEMENT TO ZERO.