

RECEIVING AND ESTIMATING REPORT

ORDER  
R 93-20311

INITIAL: \_\_\_\_\_ CUSTOMER ORDER NO.: \_\_\_\_\_ ATTN: SAM RENSI

FPS

DATE RECEIVED: 09/23/93	DATE OPENED: 09/27/93	DATE CODE: LQ 2-78	SERIAL NUMBER: A6568047	NEW SERIAL NUMBER:	MODEL AND GRADE: 700 7MM MAG ADL
ACCESSORIES: W/STUDS		L/SIGHTS			

FROM: *[Signature]* GREATER SYR MOVING & STORAGE  
ATTN: SEAN CLELAND  
6255 E. TAFT ROAD  
N. SYRACUSE NY 13212

SHIP TO: GREATER SYR MOVING & STORAGE  
ATTN: SEAN CLELAND  
6255 E. TAFT ROAD  
N. SYRACUSE NY 13212

CUST NO: 084263 C.O.D

ACCOUNT NUMBER	ACCOUNT NUMBER I/C	WRITE <input type="checkbox"/>	PROM. DATE	ESTIMATED	VIA UPS
----------------	--------------------	--------------------------------	------------	-----------	---------

GUN CONDITION

- NEW
- LIGHTLY WORN
- WORN
- VERY WORN
- UNREPAIRABLE
- MARRIED

*Send to product service for evaluation*  
*XC: S Rensi*

REPAIR CHARGE	25.00
EXCISE	
TAX	
INSURANCE	
UPS	
PARCEL POST	
TOTAL	

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	B1				
TRIGGER GROUP						F1
BOLT ASSY.		B3		D1	E2	F2
BARREL ASSY.		B4		D2	E3	F3
REC. ASSY.		B5		D3	E4	F4
WOOD			C1	D3	E5	F5
METAL			C2			

*Heavy fires on one occasion up to 2 second delay*

AIN FAULT *Upper report available to dependent customer. Both only 1988. Minimum should that the action is caused with gunny. No delay in action, and the contact has been removed on all 3 adjustment points on the trigger assembly, indicating they have been tampered with. Let's contact the manufacturer to get a replacement trigger assembly.*

VRTS *spec. at 2 1/2 lbs. increased for bolt .009*

COMMENTS *Upper report trigger assembly and that action at 1/2 normal adjustment. Opt. in question of good unit.*

*Go ahead*

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE