

RECEIVING AND ESTIMATING REPORT

COMMENTS

R ORDER
94-13872

INITIAL CUSTOMER ORDER NO.

FPS

DATE RECEIVED

DATE OPENED

DATE CODE

SERIAL NUMBER

NEW SERIAL NUMBER

MODEL AND GRADE

ACCESSORIES

W/STUDS

W/SWIVELS

SCOPE BASE

700 30-06

BDL

FROM:

SHIP TO:

GUN EXCHANGE INC
5317 W 65TH ST
LITTLE ROCK

AR 72209

GUN EXCHANGE INC
5317 W 65TH ST
LITTLE ROCKAR
72209

CUST NO: 000191 ILION

ACCOUNT NUMBER

ACCOUNT NUMBER NYC

WRITE ☐

FROM DATE

ESTIMATED

VIA

UPS

GUN CONDITION

- ☐ NEW
☐ LIGHTLY WORN
☐ WORN
☐ VERY WORN
☐ UNREPAIRABLE
☐ MARRED

REPAIR CHARGE

EXCISE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

CUSTOMER CONCERN

AMMO

FUNCTION

FINISH

ACCURACY

FIT

INSPECT

CYCLE

A1

B1

TRIGGER GROUP

B2

BOLT ASSY.

B3

BARREL ASSY.

B4

REC. ASSY.

B5

WOOD

C1

METAL

C2

MAIN FAULT

Unable to duplicate upon receipt. Inspection reveals no obvious fault, however, and trigger assembly. Removal of bolt safety from a gunny substance was found built upon both sides. With more a good cleaning.

PARTS

COMMENTS

Trigger Pin #42.245

Screw #1.008

#26345 Trigger Assembly

Replace complete trigger assembly and clean action at 1/2 normal replacement cost, as per order of good will.

Go ahead

REPAIRMAN

PROOF

CLEAN

TEST

TARGET

PATTERN

GALLERY TESTER

DATE

DATE

DATE

DATE

DATE

OFFICE COPY

RD6925 REV. 1/94

to A/S 5/19/94