

M/100 Custom Complaint

P.I. NO GUN EXAMINATION REPORT NUMBER: _____ MODEL: 700
GENERAL CONDITION: GOOD R #: 014102
OUTSIDE WORK: SCOPE MOUNTED DATE: 7-14-72
FROM: GUSTAVE GUNDERSON
FIRED AMMO TYPE: - CONRAD, MONTANA
& CONDITION: _____ GUN #: 6226860
PROOF: R.E.P. ^{ASSEMBLER 79} INSP.: 73 TEST: 87 CODE: AS-3/69
HEADING: - GA./CAL.: 22-250
BREECH OPENING: - CHECKED BY: C. PROSSER
RECOIL SHOULDERS: O.K. APPROVED: _____
CHAMBER: O.K. APPROVED: _____
TEST: NO APPROVED: _____
COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____

CONNECTOR - SEAR ENGAGEMENT .010 (MIN. IS .020) TRIGGER
PULL 2½ LBS. (3 LBS. IS MIN.) RE-ADJUSTED BY CUSTOMER.
SEAR BEARING OF CONNECTOR CROOKED. TRIGGER MEASURED-
.008 UNDER MIN. ON CONNECTOR CLEARANCE, .002 OVER MAX. ON
6 IF PIN HOLE TO TOP.

COMPLAINT: FIRES WHEN SAFETY IS PUSHED OFF TRIGGER PULL
TOO HEAVY.

INCIDENT: FOLLOW DOWN!

COMMENTS: LIGHT TRIGGER PULL RESULTS IN ERRATIC RETRACTION,
THE TRIGGER HOLDING THE CONNECTOR TOO HIGH AND
ALLOWING IT TO WORK UP .008 TO INTERFERE WITH THE
SEAR COULD MAKE RETRACTION IMPOSSIBLE, FOLLOW
DOWN WOULD RESULT.