

Carol,
pls. act up
file. Thanks,
Jim

MARCH 31, 1987

MR. DOUGLAS HAMANN
6551 TOWNLINE ROAD
WISCONSIN RAPIDS, WI 54494

Dear Mr. Hamann:

Your letter of March 6, 1987 that was addressed to our
Bridgport, Connecticut facility, regarding the accidental
firings you have experienced with your Model 700 H&D 270W-in
caliber rifle, has been forwarded to this office for handling.

We were indeed sorry to learn of your having problems
of any kind with one of our products.

Generally, the type of problem you described results
from either improper adjustment of the trigger assembly
outside our factory, from improper maintenance of the rifle,
or from inadvertent contact with the trigger while the safety
is in the "fire" position.

Please, at your convenience, return the rifle via U.P.S.
insured, to:

Remington Arms Company, Inc.

14 Hoefler Ave.

Ilion, NY 13357

Attn: J. A. STEKL, Supervisor

Product Service

Please be sure to clearly mark the two (2) test cuts of the outside
of the package "STEKL" to expedite handling.

Upon receipt, the rifle will be thoroughly inspected.