

RECEIVING AND ESTIMATING REPORT

CUSTOMER ORDER NO.			COMMENTS STKL		
DATE RECEIVED 10/02/86	DATE OPENED 10/09/86	DATE CODE	SERIAL NUMBER 6788266	MODEL AND GRADE 700 30-06 BDL	ORDER R 86-19405
ACCESSORIES W/STUDS					

BOTTOM HALF SEE THRU MTS

FROM:	SHIP TO:
GIOVANONI HDWE., INC. 303 SILVER ST. HURLEY, WI.	
54534	

COUNT NUMBER	PROM. DATE	ESTIMATED	VIA UPS
PAIR CHARGE	TAX ST	INSURANCE	UPS
TAX CITY	PARCEL POST	TOTAL \$	

CONDITION: ☐ NEW ☒ SLIGHTLY WORN ☐ VERY WORN ☐ MISUSED ☐ QUOTE

CUSTOMER'S COMPLAINT
"When I load up, push in the bolt & pull down the bolt handle, it goes off"

MAIN FAULT
Under side of receiver & trigger assembly is loaded with partially solidified oil - trigger is very sluggish even in 75° office - bolt stop is nearly inoperative from dried out

RTS
Clean up (de-grease) trigger assembly re-test.
Lock was broken in shipment!

FOR COMPUTER REF. ONLY			PROOF
			(CLEAN) (TEST) (TARGET)
			REPAIRMAN

OFFICE COPY

074025 REV 7-8