

COMMENTS

R ORDER
72-08562

ATTN J STEKL TOE OF STOCK BROKEN

FROM:	SHIP TO:
HARLOW, CLINTON RT 8 BOX 5 LIANO TX 78643	HARLOW, CLINTON RT 8 BOX 5 LIANO TX 78643

CUST NO: 060127 C-D.D

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	B1				
TRIGGER GROUP	<i>Gun damaged while shooting Remington ammunition</i>					F1
BOLT ASSY.		B3			E2	F2
BARREL ASSY.		B4		D1	E3	F3
REC. ASSY.		B5		D2	E4	F4
WOOD			C1	D3	E5	F5
METAL			C2			

MAIN FAULT

MAIN FAULT *As above - can explain damaged strata and bore - however unable to make positive determination as to cause.*

(Note*) - freeze-dried was broken during shipment of rft from Boulder, CO to Ithaca, NY

[illegible]

OFFICE COPY

BD6925 REV. 8/91

PPS 02201