

Remington



REMINGTON ARMS COMPANY, INC.

140 & Remington Road
Lonoke, AR 72086
501/676-4197

CUSTOMER:

Mrs. Clinton Harlow

Rt. 8, Box 5

Llano, TX 78643

Date: 2/28/92

File # 34129

PROPERTY DAMAGE

The damaged Mdl 700 .222 Rem. Mag. rifle and 19 (2 fired, 17 unf.) R222M1's you returned has (have) been received and submitted to our ballistics laboratory for examination. A report of our test results will be sent to you in approximately 6 weeks.

PLEASE RETURN EXHIBITS TO P.S.O.

Any inquiry should
show above file number

W. T. SMITH
Product Service Supervisor

RECEIVED 2/28/92

PD 1186 X
2186

To: Ballistics

Code: H15P 12/77

Firearm Mfg:

Rem. Mdl. 700 .222 Rem
S/N 201936

Complaint: Case separation/gun damage

Test for: 1. Shoot for V&P

2. Cause of case separation

3. Comment

4.

5.

Report: No defect found. The case appeared to separate in the most probable spot after several reloadings - See attached sheet.

SHELLS HAVE NOT BEEN RELOADED

V&P: A LITTLE LOW

RECEIVED

Unconfirmed

MAR 06 1992

Approved:

Date:

PRODUCT SERVICE

Approved:

Date:

Returned to Product Service Office:

Reidy J Buckmaster

Date:

3-5-92