

3-3/ 443-452

P.I. 725 GUN EXAMINATION REPORT NUMBER: 57

MODEL: 700 BSL

GENERAL CONDITION: Good

R # : 08810

OUTSIDE WORK: SCOPE SCREWS REMOVED

DATE: 3-9-79

FROM: P. HARRISON

FIRED AMMO TYPE: U N K1000 V

1312 B000 V BELAY ST.
PLASTIC 22-1220

& CONDITION: —

GUN # : A6305900

PROCP: REPOV INSP.: U TEST: 111

CODE: K1-5-76

HEADING: OK

GA./CAL.: 243

BREECH OPENING: OK

CHECKED BY: M. H. - 90V

RECOIL SHOULDERS: OK

APPROVED: Sgt 3/30/79

CHAMBER: OK

APPROVED: PL 3/30/79

TEST: —

APPROVED: PL 3-30-79

COMPONENT CONDITION: (Damaged, Broken, Old Style)

APPROVED: PL 3-30-79

SHALL DENT IN WOOD

DOB 3-30-79

UPON METAL AT Muzzle

COMPLAINT: RIFLE DISCHARGED WHEN SHOT
POSSIBLE FORWARD

INCIDENT: BLEW A HOLE IN BED OF PICK
UP TRUCK

COMMENTS: Unable to duplicate incident. Weight
A full screw & overtravel screw not sealed indicating
then have been activated outside of Remington.