E.F. Barratt J.E. Praiser E.G. Larson J.H. Chisnall R.B. Sperling F.D. Cole

forward the gem discharged, and blew a hole in the bed of her pick-up truck. She incide she touched nothing but the forearm of the rifle and the sefety with her thumb. Since this is an unusually accurate rifle and I don't want to get sid of it, I called h. b. Sherman at Bridgeport, lann, and he suggested I sand it.

19

1 4, 1979

el 700 BDL .243 Win. ch allegedly fired tion.

and trigger assembly ave described. All to be normal, inr, it appears that ant scraws have been ad by the sealant

any, Inc., cannot acnis incident. We can to the off position, ar. When the safety fted off of the trigffort is required to unector to be moved ition, on moving the fire.

stances that could and, as a gesture of ang with your present at no ifle is restored, or,

the rifle can be returned as received. We will await your decision and reply.

Thank you for having afforded us this opportunity to examine your rifle and to be of service.

Sincerely,

J.A. Stekl, Supervisor Firearms Product Service

JAS: tpp