281-2803

Ray Harrison 1312 Roundelay St. Bastrop, Fa. 71220 E.F. Barrett

J.E. Preiser

E.G. Larson

J.H. Chisnall R.B. Sperling

F.D. Cole

810

1.4, 1979

Shile deer hunting this fast
stason, I saw a buck and Raised
my rifle to shoot, when I pushed
the safety forward, the gum west
off scaring me and the deer putly
good. I didn't get too upset
about it because I thought may
be I brushed the trigger wath my
finger.
I forwer, my daughter borround it
of go deer hunting and at the conclusion of the hunt she wanted
to unload the gum.

sl 700 BDL .243 Win. th allegedly fired tion.

ind trigger assembly ive described. All to be normal, in:, it appears that int screws have been in by the sealant.

ny, Inc., cannot acis incident. We can o the off position, r. When the safety ted off of the trigfort is required to nector to be moved tion, on moving the fire.

tances that could and, as a gesture of ag with your present other assembly at no life is restored, or, will await your deci-

the rifle can be returned as received. We will await your decision and reply.

Thank you for having afforded us this opportunity to examine your rifle and to be of service.

Sincerely,

J.A. Stekl, Supervisor Pirearms Product Service

JAS: top

PPS 02218

مارد التوار