

P.I. Y = 1 GUN EXAMINATION REPORT NUMBER: 57 MODEL: 730 PSL
GENERAL CONDITION: F-220 R#: 03810
OUTSIDE WORK: SCOPE SCREWS REMOVED DATE: 3-9-79
R. H. + R.R./JG/Y
FIRE AMMO TYPE: U/N 7.62MM FROM: 1312 P-301-3-02 S
R-45-3-02 13-02-225
A CONDITION: - GU # : A6305790
PROC: 5-200 INSP.: U TEST: 111 CODE: K1-5-76
HEADING: 30° GA./CAL.: 243
BREECH OPENING: 1- CHECKED BY: 3-2-831
RECOIL SHOULDERS: 2+ APPROVED: SAR 3/30/79
CHAMBER: 3+ APPROVED: 3/18/80/79
TEST: - APPROVED: R/AB 3-29-79
COMPONENT CONDITION: (Damaged, Broken, Old Style)
CHAMBER SCREW WAS MISSING APPROVED: 180 3-30-79
NO METAL - NO EVIDENCE

COMPLAINT: P1-E DISCHARGED WHEN S=1
CHAMBER FLOOR = PO
INCIDENT: BLUNT 3-02-79 3 SEC 1 = P-2
UP TRAIL

COMMENTS: Unable to duplicate incident. Weight
A full screw & one loose screw not sealed indicating
they have been machined outside of Remington.