

ATTENTION Rodger POTTER  
REMINGTON SERVICE DIVISION

My. REMINGTON 700 has a defective  
Trigger/Safety.

A few weeks EARLIER while unloading it  
it discharged (in the house). This happened when  
I moved the safety to fire position to operate  
the Bolt. I've gotten the ~~problem~~  
problem to repeat on several occasions  
while the gun was unloaded.

This was done by cocking the gun  
and rapping on the stock as if it were  
riding in a bumpy truck.

Also I use this gun for VARMINT  
hunting and TARGET shooting. A light trigger  
pull is a MUST AFTER needed repair could  
you adjust trigger pull? ABOUT 2 LBS or so.

Thank you

SN 6607224  
Rem 700  
22-250

JON A. HAYNES  
RR 3 Box 211  
CLINTON IN.  
47842