

P.I. YES GENERAL CONDITION USED NUMBER: 62 MODEL: 700
OUTSIDE WORK: SIGHTS AND STOCK MISSING R #: 02321
SCOPE BASE ADDED DATE: 1-15-79
FIRED AMMO TYPE: UNKNOWN FROM: VEIL-L. HEBGLAND
& CONDITION: STEAMBOUT, SPY, COLORADO
PROOF: (REP) A INSP.: 58 TEST: 87 GUN #: 6359039
HEADING: GA./CAL.: 264 WIN. MAG CODE: XT = 12-70
BREECH OPENING: OK CHECKED BY: M-HARDY
RECOIL SHOULDERS: OK APPROVED: RDH 2/16/79
CHAMBER: OK APPROVED: RDH 2/16/79
TEST: OK APPROVED: RDH 2-16-79
COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: RDH 2-16-79
BRIGHT METAL SHOWING ON BB
AND FLOOR PLATE.

COMPLAINT: WEAPON DISCHARGED WHEN SAFETY
WAS JOSHED TO OFF SAFE POSITION
INCIDENT: SHOOT HOLE IN BACK OF PICKUP TRUCK
CAB, A VEST AND PICK UP BOX.

COMMENTS: Malfunction appears to have been caused by
excessive oil in trigger mechanism. RDH confirmed
malfunction at low temperature test (0°F).
Trigger has been adjusted outside Kernington
as evidenced by block lacquer on adjusting screws.
Engagement .050.