

RECEIVING AND ESTIMATING REPORT

CUSTOMER ORDER NO.		COMMENTS			
RECEIVED 02/91	DATE OPENED 01/09/91	DATE CODE 0E 7-84	SERIAL NUMBER B6624581	MODEL AND GRADE 700 270 WIN BDL	ORDER R 91-00734
SSORIES W/STUDS		SCOPE BASE			

M:

HENRY'S GUNS "R" US
RT 11 N MAIN ST
RT 1 BOX 442
MT JACKSON

VA 22842

SHIP TO:

HENRY'S GUNS "R" US
RT 11 N MAIN ST
RT 1 BOX 442
MT JACKSON

VA 22842

UNIT NUMBER	ACCOUNT NUMBER N/C	WRITE ☐ CLEAN/TEST	PROM. DATE	ESTIMATED	VIA UPS
-------------	--------------------	---	------------	-----------	------------

CHARGE	TAX	INSURANCE	UPS	PARCEL POST	TOTAL
--------	-----	-----------	-----	-------------	-------

CONDITION:

☐ NEW

☒ SLIGHTLY WORN

☐ VERY WORN

☐ MISUSED

☐ MARRED

MAKER'S REQUEST

customer says rifle will fire when bolt closes and also when trigger is pulled a delay happens before gun fires.

trigger has been completely mis-adjusted outside of factory - resultant firing from all adjustment screws. 1) insufficient over travel 2) insufficient engagement of trigger pull out of specs at 65 pounds. Trigger and motor will maintain and re-position in working because of incorrect over-travel.

Send quotation for new trigger assembly at 1/2 normal cost, as good-will gesture.

REPAIRMAN LEE	PROOF	CLEAN	TEST	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

STEK/

RD6925 REV. 7/90