

Jan 7th 1982

Remington Arms Co. Inc.
Arms Service Dept.
Ilion, N.Y. 13357

Att: Mr. El

For our phone conversation on 1-7-82
I am returning 7041 minus 700 B.D. 30.06
for you to replace. The gun will
discharge when the safety is moved
to the fire position. This has happened
twice. The last time removed part of
the dash and front of my motor home.

Please see other instructions I am sending
the gun for collect.

Thank you for your help

Dr. H. H. H.
6430 Newbold Dr.
College Park, Georgia 30537

Record - 100 1956
Serial No. - 46 334-714
14000000 271301
Serial No. - 5792