

P.I. No GUN EXAMINATION REPORT NUMBER: _____ MODEL: 700
GENERAL CONDITION: NEW R #: 026064
OUTSIDE WORK: SCOPE MOUNTED DATE: 12-5-72
FROM: HERTER'S INC.
FIRED AMMO TYPE: - OLYMPIA, WASH.
& CONDITION: _____ GUN #: 6524373
PROOF: R.E.P.-B INSP.: 74 TEST: 97 CODE: CW = 4/72
HEADING: O.K. GA./CAL.: 3006
BREECH OPENING: - CHECKED BY: C. PROSSER
RECOIL SHOULDERS: O.K. APPROVED: _____
CHAMBER: O.K. APPROVED: _____
TEST: No APPROVED: _____
COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____

SEAR-TRIGGER CONNECTOR ENGAGEMENT .025(MIN IS
.020) CONNECTOR = 1.088 MODEL DRAWING = 1.080, TRIGGER
MEASURES 1.074, MODEL DRAWING = 1.076

COMPLAINT: "FIRES WHEN SAFETY IS PUSHED OFF"

INCIDENT: FOLLOW DOWN

COMMENTS: THE CUSTOMER'S MALFUNCTION COULD NOT BE
DUPLICATED, HOWEVER, THE .007 OVER MAX. CLEARANCE
BETWEEN THE TRIGGER AND CONNECTOR WILL ALLOW
THE CONNECTOR TO INTERFERE WITH THE SEAR AND
FAILING TO RETRACT INTO COCKED POSITION, CAUSE
A FOLLOW-DOWN.