

RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER
R 94-10227

INITIAL CUSTOMER ORDER NO.

FJB

W/ SOFT CASE

DATE RECEIVED
03/18/94DATE OPENED
03/21/94DATE CODE
PZ 6-75SERIAL NUMBER
6881186

NEW SERIAL NUMBER

MODEL AND GRADE
700 243

BDL

ACCESSORIES

W/STUDS

SCOPE BASE

L/SIGHTS

FROM:

SHIP TO:

HIGHSMITH GUNS
3968 WEST 300 SOUTH
NEW PALESTINE

IN 46163

HIGHSMITH GUNS
3968 WEST 300 SOUTH
NEW PALESTINEIN
46163

CUST NO: 014391 C-D-DL

ACCOUNT NUMBER

ACCOUNT NUMBER N/C

WRITE ☐

FROM DATE

ESTIMATED

VIA

5-6

UPS

GUN CONDITION

- ☐ NEW
☐ LIGHTLY WORN
☐ WORN
☐ VERY WORN
☐ UNREPAIRABLE
☐ MARRED

REPAIR CHARGE

EXCISE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE		F1				
TRIGGER GROUP		B2			E1	F1
BOLT ASSY.		B3				
BARREL ASSY.		B4		D1	E3	F3
REC. ASSY.		B5		D2	E4	F4
WOOD			C1	D3	E5	F5
METAL			C2			

When we received the rifle we would not insert bolt assembly. The bolt stop
was covered with a heavy, thick, and gummy substance. The rifle
would not function as designed. We could not duplicate the unintentional
locking action. They said we should use 4 1/2 lbs. of sand. OK.

The action is also covered with this gummy substance. Rifle needs a good
cleaning. What then would be required at time to make rifle
function.

Repaired trigger assembly
at 1/2 normal
replacement cost as per spec.

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTE
SWT					
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6925 REV. 1