

M/700 Customer
Complaint

P.I. No GUN EXAMINATION REPORT NUMBER: _____

MODEL: 700 BDL

GENERAL CONDITION: NEW

R # : 015571

OUTSIDE WORK: No

DATE: 8-14-72

FROM: HIGHSPIRE SPTG.
GOODS INC.

FIRE AMMO TYPE: FACTORY LOADS

HIGHSPIRE, PA.

& CONDITION: _____

GUN # : 6312165

PROOF: R.E.P.-E ASSEMBLER 74 INSP.: 74 TEST: 49

CODE: LT= 2/70

HEADING: MAX. WITH ASSEMBLY MAX.

GA./CAL.: 3006

BREECH OPENING: -

CHECKED BY: C. PROSSER

RECOIL SHOULDERS: EXCESSIVE RADIUS BACK OF ^{LUGS.}

APPROVED: _____

CHAMBER: O.K.

APPROVED: _____

TEST: No

APPROVED: _____

COMPONENT CONDITION: (Damaged, Broken, Old Style)

APPROVED: _____

SEAR-TRIGGER CONNECTOR ENGAGEMENT .010 (MIN. IS .020)

BURRS ON SIDES OF UPPER PART OF TRIGGER SHOW FRICTION

MARKS, POOR COLOR ON BARREL AT REAR SIGHT.

COMPLAINT: "FIRES JUST AS BOLT IS CLOSED."

INCIDENT: FOLLOW DOWN

COMMENTS: THE TRIGGER BIND WITH UNDER MIN. ENGAGEMENT

CAUSED ERRATIC TRIGGER RETRACTION AND FOLLOW

DOWN.