

RECEIVING AND ESTIMATING REPORT

INITIAL		CUSTOMER ORDER NO.		COMMENTS			
FPS							
DATE RECEIVED	DATE OPENED	DATE CODE	SERIAL NUMBER	MODEL AND GRADE		ORDER	
12/17/90	12/20/90	BQ 1-78	A6560972	700 270 WIN BDL		R 90-3338	
ACCESSORIES		SCOPE BASE					

FROM:

R. L. "SKEET" HILL
P.O. BOX 457
209 RAYMOND ST. HWY 45 N
VERONA MS 38879

SHIP TO:

R. L. "SKEET" HILL
P.O. BOX 457
209 RAYMOND ST. HWY 45 N
VERONA MS
38879

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE ☐	CLEAN/TEST	PROM. DATE	ESTIMATED	VIA
						UPS

REPAIR CHARGE	TAX	INSURANCE	UPS	PARCEL POST	TOTAL
---------------	-----	-----------	-----	-------------	-------

GUN CONDITION: ☐ NEW ☐ SLIGHTLY WORN ☐ VERY WORN ☐ MISUSED ☐ MARRED

CUSTOMER'S REQUEST

"Complaint - goes off"

MAIN FAULT: Trigger and safety assembly operates properly - safe cannot be made to malfunction. However, trigger has been adjusted out of factory - trigger pull - 2 3/4#, rear lift 0.005". Trigger assembly is extremely dirty - improper maintenance. Insufficient post-travel.

PARTS: Send quotation to clean and properly re-adjust present trigger assembly or we can install a new trigger assembly at 1/2 normal cost as a good-will gesture if it will better restore confidence in the rifle.

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
BW					
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6925 REV. 7