

RECEIVING AND ESTIMATING REPORT

COMMENTS

to Product Service

ORDER
R93-25212

INITIAL
FPS

CUSTOMER ORDER NO.

DATE RECEIVED

DATE OPENED

DATE CODE

SERIAL NUMBER

NEW SERIAL NUMBER

MODEL AND GRADE

11/16/93

11/19/93

DP 9-67

96645

600 243 WIN

ACCESSORIES

W/STUDS

W/SWIVELS

FROM:

[Signature]
HITCHIN POST SPORTS
124 N MONTANA
DILLON

SHIP TO:

HITCHIN POST SPORTS
124 N MONTANA
DILLON

MT 59725

MT
59725

CUST NO:003292 C.O.D

ACCOUNT NUMBER

ACCOUNT NUMBER W/C

WRITE ☐

PROM. DATE

ESTIMATED

VIA

UPS

GUN CONDITION

- ☐ NEW
- ☐ LIGHTLY WORN
- ☐ WORN
- ☐ VERY WORN
- ☐ UNREPAIRABLE
- ☐ MARRED

REPAIR CHARGE

EXCISE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

20.

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	B1				
TRIGGER GROUP		B2			E1	F1
BOLT ASSY.		B3			E2	
BARREL ASSY.		B4		D1	E3	F3
REC. ASSY.		B5		D2	E4	F4
WOOD			C1	D3	E5	F5
METAL			C2			

MAIN FAULT

My 1967, upon receipt, could not adjust custom crown. Examination of action and trigger assembly revealed that the rifle was poorly maintained. Trigger would not set, and heavy build up of lubrication. Safety assembly works better than normal.

PARTS

COMMENTS

Replaced trigger spring and clean action at 1/2 normal cost

[Signature]

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTE
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6925 REV.