

CONFIDENTIAL

Remington Arms Company Inc.
RESEARCH & DEVELOPMENT TECHNICAL CENTER
315 WEST RING ROAD
ELIZABETHTOWN, KY 42701

In addition to the descriptions of demerits listed above, there will be special occurrences or unique items that will require the placement of demerits. These will be handled as they occur. The Audit Team and Staff Supervision will establish the demerit level for these occurrences.

In some instances, in place of Demerits, the item being reviewed could be listed as an ACTION ITEM and assigned to a specific department or engineer to review and report on. Based upon the report of the findings, a Demerit Level would be established if needed.

FIFTY DEMERITS: A Fifty-Demerit Classification indicates the firearm being reviewed does not meet the criteria established for the proper manual function of that firearm. If a Fifty-Demerit Classification is placed upon a reviewed firearm, this would mean immediate action is taken to identify the problem and correct it.

In addition the following will be checked on each sample:

- Check the muzzle for the presence and condition of the Crown.
- Make sure that the Metal to Stock fit is uniform.
- Check the fit of the Recoil Pad to the Stock.
- Check each sample for the presence of Dirt, Lint and Excess Oil.

Examine the samples for any other unusual appearance discrepancies that may not be listed above.

Make a list of the discrepancies and their assigned demerit values that are found on each test sample and photograph if necessary to document the finding. Calculate the average demerits per gun.

TLW0300B – Packaging Audit

The Packaging will be audited, as the firearms are unpacked. Each shipping box will be examined for:

J.R.Snedeker

Page 8 of 51

9:45 AM 9/21/00

TLW0300

Remington Confidential

Revision # 0