

RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER
R 92-24645

INITIAL JJM	CUSTOMER ORDER NO. 23375				
DATE RECEIVED 11/12/92	DATE OPENED 11/17/92	DATE CODE LA 2-B0	SERIAL NUMBER A6857301	NEW SERIAL NUMBER	MODEL AND GRADE 700 30-06 BDL
ACCESSORIES W/STUDS		SCOPE BASE L/REAR SIGHT			

FROM:

HUNTINGTONS SPTSMAN
601 ORD DAM BLVD
PO BOX 991
OROVILLE

CA 95965

SHIP TO:

HUNTINGTONS SPTSMAN
601 ORD DAM BLVD
PO BOX 991
OROVILLE

CA

95965

CUST NO: 000228 WILM L

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE ☐	CLEAN/TEST	PROM. DATE	ESTIMATED 12-1	VIA UPS
GUN CONDITION						REPAIR CHARGE
☐ NEW						EXCISE
☐ LIGHTLY WORN						TAX
☐ WORN						INSURANCE
☐ VERY WORN						UPS
☐ UNREPAIRABLE						PARCEL POST
☐ MARRED						TOTAL

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	B1				
TRIGGER GROUP	1) "in fire when the safety was taken off"	B2			E1	
BOLT ASSY.		B3			E2	
BARREL ASSY.	2) "Also install a safety that lets the bolt open when it's on"	B4			E3	
REC. ASSY.		B5		D2	E4	F4
WOOD			C1	D3	E5	F5
METAL			C2			

MAIN FAULT

Could not duplicate complaint. However, removal of the action from the shop revealed that the trigger assembly had been improperly adjusted out of factory. Trigger interaction is not inconsistent with positive, because weight of full sized bolted out for fire. This condition could possibly account for the complaint that was noted. Trigger pull 3 1/4 pounds; rear lift .009"

PARTS

COMMENTS

1) Offer to replace trigger assembly with new style (no bolt lock) for \$125.00, as gesture of good-will.

REPAIRMAN BSW	PROOF	CLEAN	TEST	TARGET	PATTER
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

R06925 REV. 11

PPS 02500