

CUSTOMER ORDER NO

W/1 SPENT CASE

DATE RECEIVED	DATE OPENED	DATE CODE	SERIAL NO.	MODEL AND GRADE	ORDER
12/02/85	12/09/85	BB 1-81	B 6282261	700 30-06 BDL	R 85-24

SWIVEL STUD

FROM:

SHIP TO:

SHANNON HUSTON
704 GALAXY
HARRISONVILLE, MO.

64701

FROM DATE	ESTIMATED	VIA
		UPS
REPAIR CHARGE	INSURANCE	UPS
PARCEL POST	TOTAL	\$

GUN CONDITION: ☐ NEW ☒ SLIGHTLY WORN ☐ VERY WORN ☐ MISUSED ☐ QUOTE

CUSTOMER'S COMPLAINT

"Fired upon releasing safety - happened twice"

MAIN FAULT

Could not duplicate alleged malfunction - however bottoming receiver and trigger assembly dripping wet with oil.

DEMERIT CODE

PARTS

Clear oil off rifle and install new style trigger assembly (no bolt).
at no-charge.

Please expedite!

1/3/86
Jas.

FOR COMPUTER REF. ONLY

PROOF

(CLEAN) (TEST) (TARGET)

REPAIRMAN

OFFICE COPY

RDev.

PPS 02518