

February 14, 1989

Remington Arms Company
14 Hoefler Ave.
Ilion, New York 13357

Attention: Roger Potter

Subject: Remington 270 Rifle, serial number # B 6 89952

Dear Sir:

We are sending this rifle as instructed by Lorraine.

My husband Paul Allen Myhand, was on a hunting excursion Saturday, January 21, 1989 with a friend. Allen placed the loaded rifle on its case in our truck and was entering the truck to move to another location within the hunting grounds when the rifle discharged into the floorboard. Upon Allen's investigation of the truck the bullet entered the bell housing going through the torque converter of the transmission and piercing the fly wheel, he is not sure as to whether or not the bullet penetrated the engine block. We have not had the truck examined by a mechanic as of yet.

I purchased the rifle from The Rod and Gun Shop in Montgomery, Alabama in the Fall of 1987. Allen had the trigger mechanism replaced upon receipt of your recall at Todd's gun shop in Montgomery, Alabama, in either late August of early September of 1988. Upon replacement of the trigger mechanism by Todd's, Allen had expressed doubt as to whether or not Todd's had actually replaced the mechanism.

If you have any further questions please contact me, I will be awaiting for your reply and determination in this matter.

Respectfully,


Donna Myhand