

RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER
R 93-23369

INITIAL JJM	CUSTOMER ORDER NO.					
DATE RECEIVED 10/27/93	DATE OPENED 11/01/93	DATE CODE BR 1-68	SERIAL NUMBER 323758	NEW SERIAL NUMBER	MODEL AND GRADE 700 243	BDL/VAR
ACCESSORIES W/STUDY		SCOPE BASE				

FROM:

SHIP TO:

J J R GUN SHOP
632 SECOND ST
PORTSMOUTH

OH 45662

J J R GUN SHOP
632 SECOND ST
PORTSMOUTHOH
45662

CUST NO:005107 C.W.D.L

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE ☐	PROM. DATE	ESTIMATED 11-13-93	VIA UPS
GUN CONDITION ☐ NEW ☐ LIGHTLY WORN ☐ WORN ☐ VERY WORN ☐ UNREPAIRABLE ☐ MARRED			REPAIR CHARGE 25.00 EXCISE TAX INSURANCE UPS PARCEL POST TOTAL		

Product Service

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	B1				
TRIGGER GROUP	"	B2			E1	F1
BOLT ASSY.		B3			E2	F2
BARREL ASSY.		B4			E3	F3
REC. ASSY.		B5		D2	E4	F4
WOOD			C1	D3	E5	F5
METAL			C2			

MAIN FAULT

Rifle mfg 1968, unable to dislodge custom crown.
Examination revealed that the trigger adjustment screw has been too
tight, and that screw, indicating it has been adjusted to trigger unit
normal setting. Custom crown must be replaced with a standard
to bolt stop release.

COMMENTS

Replace complete trigger assembly
& clean action at 12 normal
upstream that in action of good and

REPAIRMAN

PROOF

CLEAN

TEST

TARGET

PATTERN

GALLERY TESTER

DATE

DATE

DATE

DATE

DATE

OFFICE COPY

RD6925 REV. 1/9.