

Dr. Sydney V. Jackson  
2296-A 36th St.  
Los Alamos, N.M. 87544  
(505) 662-2192  
November 21, 1979

Remington Arms Co. Inc.  
Bridgeport, Connecticut 06602

Dear Sirs:

On July 5, 1979 I purchased a Remington 700 ADL 30-06 rifle, serial #A6485099. During the summer the rifle was fired several times to align the iron sights. And in early November the rifle was again fired to align a telescope sight.

Then on a hunting trip 11/14 - 11/18 the rifle malfunctioned in such a way as to endanger all members of the hunting party. On three occasions, after the rifle had been carried for some time with the chamber loaded and the safety on safe, the rifle fired immediately upon releasing the safety. Luckily there were no injuries or property damage, although a good shot was lost on the third occasion.

I request that this defect be remedied or that the rifle be replaced as soon as possible, and that some form of compensation be provided for the inconvenience this has caused me, the danger this defect has placed me in, and ( if the rifle is replaced ) the investment I have made in money and time in setting the rifle up for hunting. A copy of this letter is being sent to my attorney for his files.

Sincerely yours,



Dr. Sydney V. Jackson

cc/ Byron Treaster, Attorney

I have flushed the trigger assembly with compressed grade methanol and then lightly lubricated it. The problem has not occurred with an empty chamber.