

Setup fee

JAY'S SPORTS

XC
Lind Supply

SUGGEST
1/2 OR FULL PAY
FOR NEW FIRE
CONTROL!

FINGERPIECE OF TRIGGER HAS BEEN
BADLY BENT DOWN AND REARWARD,
THE END OF THE TRIGGER CONTACTS
THE INSIDE OF THE TRIGGER GUARD
BOW.

DEPENDENT ON HOW TIGHT
THE ACTION SCREWS ARE AND
② NORMAL "ROLL" OF THE ACTION
IN THE STOCK, THIS GUN WILL
FSR AND THEN FOLLOW DOWN.
(NEVER FIRES ON BOLT CLOSE)

ALL SEALS REMOVED — BUT
FIRE CONTROL SPECS OK.

F.C. HAS BEEN REMOVED FROM
ACTION, AND SAFETY FROM F.C. TOO.