

RECEIVING AND ESTIMATING REPORT

COMMENTS

STAINLESS STEEL

INITIAL JJM	CUSTOMER ORDER NO.					
DATE RECEIVED 10/01/90	DATE OPENED 10/10/90	DATE CODE AU 3-71	SERIAL NUMBER 6412588	MODEL AND GRADE 700 17REM		ORDER R 90-2620
ACCESSORIES L/MAG BOX		L/WOOD	L/FOLLOWER	L/MAG SPRING SCOPE BASE L/SIGHTS		

FROM:

JIM'S SPORTING GOODS
RT 2
BOX 90 B
PARIS MO 65275

SHIP TO:

JIM'S SPORTING GOODS
RT 2
BOX 90 B
PARIS

MO
65275

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE ☐	CLEAN/TEST	PROM. DATE	ESTIMATED	VIA UPS
----------------	--------------------	--------------------------------	------------	------------	-----------	------------

REPAIR CHARGE	TAX	INSURANCE	UPS	PARCEL POST	TOTAL
---------------	-----	-----------	-----	-------------	-------

GUN CONDITION:

☐

NEW

☐

SLIGHTLY WORN

☒

VERY WORN

☐

MISUSED

☐

MARRED

CUSTOMER'S REQUEST

"The firing pin falls when the bolt is closed".

MAIN FAULT

Trigger assembly has been improperly adjusted outside the factory.
Insufficient cam engagement; trigger pull also out of spec at 2"
Brightest factory sealant has been removed from adjustment screws

PARTS

Send repair quotation for replacement
trigger assembly at 1/2 barrel price
no question of good will.

Repl is 19 years old

REPAIRMAN BU	PROOF	CLEAN	TEST	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6925 REV.